














Map 2. Brush Creek Community Partners Catchment Area

Parcel Level Land Use and Infrastructure Conditions, 2001

Data Source: City of KCMo 2001 Housing Conditions Survey
Produced by the Center for the City at UMKC

-  Target area boundary
-  Corridor thoroughfares
-  Corridor Buffers
- Parcels with no structure
-  Vacant lot
-  Park
-  Parking lot
- Residential parcels - infrastructure average ratings
-  4.5 - 5.0 Excellent
-  3.5 - 4.5 Good
-  2.5 - 3.5 Sub-Standard
-  1.5 - 2.5 Seriously Deteriorated
-  1.0 - 1.5 Severely Deteriorated
-  Non-residential



UMKC Volker Campus

Midwest Research Institute

Stowers Institute for Medical Research

